## L.V.T.

## **Moduleo Transform Herringbone**

## **Specifications:**

















Dimensional stability

Slip resistant

Castor wheel resistant

Thermal resistance

Long lasting

Stain resistant

Light fastness

Stocked in New Zealand

23 – 33
2.50 mm
0.55 mm
Protectonite®
4059 g/m <sup>2</sup>
15.80 x 63.20 cm
24 pc/box, 2.40 m <sup>2</sup> /box
Bfl-S1
8.1 kW/m2
MSR-A2, MSR- B1
≤ 0.35 mm
DS
R10
Norm: ≤ 0.10 mm, Average result measured ≤ 0.03 mm
No cracks, no damage
Norm: ≤ 0.25 %, Average result measured ≤ 0.05 %
0.27 w/(m.K)
0.0100 m <sup>2</sup> K/W
< 2 kV
3 dB
No damage to wearlayer, no delamination
E1
Good
≥ 6
Suitable, max 27°C
25 Residential / 10 Commercial

- RUBBER MIGRATION: This is a condition that can cause vinyl to discolour. Migration occurs when latex or rubber products
  such as shoes, rubber backed mats or rubber soled slippers come into contact with vinyl over a period of time. This is not a
  manufacturing fault and therefore is not covered under our warranties.
- Warranties are extended to the original purchaser of the product only and are not transferable.

Please contact us on 03 366 9839 to request any samples or other product details.

international flooring solutions

p 03 366 9839 e office@robertmalcolm.co.nz 10 Establishment Drive, PO Box 914, Christchurch 8140, New Zealand robertmalcolm.co.nz

